

SAFETY DO'S

- -Wear safety glasses at all times
- -Wear long pants
- -Wear close-toed shoes, preferably suede/leather/canvas.
- -Wear cotton instead of synthetic (cotton burns off, polyester melts on)
- -Wear gloves when handling hot materials
- -Wear ear protection
- -Ask am instructor, a monitor, or the shop tech for help
- -Bring any safety concerns to an instructor, a monitor, or the shop technician
- -Refer to posted warnings near machinery before use
- -Be sober, mindful, and kind

SAFETY DONT'S

- -DONT wear shorts!
- -DONT wear loose fitting clothing (entanglement hazard!)
- -DONT wear gloves when operating machinery (entanglement hazard!)
- -DONT wear jewelry (entanglement / degloving hazard!)
- -DONT use headphones/airpods in the shop
- -DONT look at the welding arc without proper eye protection
- -DONT use equipment on which you have not recieved training

ALWAYS REMEMBER

- -Your safety is more important than a grade
- -If you dont know, ASK
- -Monitors, instructors, and the shop technician are here for YOU
- -Make use of the resources around you.